

To

Springfield Public School,
Ambala-Chandigarh Highway,
Ambala.

Memo. No.

4524

Dated: -

16/7/18


Subject: - Request to issue a certificate regarding School Building Safety.

Reference:- Your office letter dated 25.06.2018.

It is submitted that School building has been inspected by the Sub Divisional Engineer, Provincial Sub Division No.6 and who have reported that building is structurally safe as on today and Safety Certificate is hereby given upto the period 2018-19 with following conditions:

1. Building of this School will be repaired every year.
2. Water should not be allowed to stagnate around and on the roof of the building.
3. If building is found cracked from anywhere, the same should be got vacated immediately and same should be got repaired immediately.
4. Institution will be responsible for safety of building from every angle and firefighting equipment should be in functional condition.
5. If the building of this school is to be extended, the same should be first approved from architect.

DA/ Nil.


Executive Engineer,
Provincial Division No.1,
PWD (B&R), Ambala Cantt.

Endst.No.

Dated:

Copy to the above is forwarded to the Sub Divisional Engineer, Provincial Sub Division No.6, PWD B&R, Ambala Cantt for information w.r.t his office Memo. No.393 dated 06.07.2018.

DA/ Nil.

50
Executive Engineer,
Provincial Division No.1,
PWD (B&R), Ambala Cantt

To

Springfield Public School,
Ambala-Chandigarh Highway,
Ambala.

Memo. No.

4524

Dated: -

16/7/18


Subject: - Request to issue a certificate regarding School Building Safety.

Reference:- Your office letter dated 25.06.2018.

It is submitted that School building has been inspected by the Sub Divisional Engineer, Provincial Sub Division No.6 and who have reported that building is structurally safe as on today and Safety Certificate is hereby given upto the period 2018-19 with following conditions:

1. Building of this School will be repaired every year.
2. Water should not be allowed to stagnate around and on the roof of the building.
3. If building is found cracked from anywhere, the same should be got vacated immediately and same should be got repaired immediately.
4. Institution will be responsible for safety of building from every angle and firefighting equipment should be in functional condition.
5. If the building of this school is to be extended, the same should be first approved from architect.

DA/ Nil.


Executive Engineer,
Provincial Division No.1,
PWD (B&R), Ambala Cantt.

Endst.No.

Dated:

Copy to the above is forwarded to the Sub Divisional Engineer, Provincial Sub Division No.6, PWD B&R, Ambala Cantt for information w.r.t his office Memo. No.393 dated 06.07.2018.

DA/ Nil.

59
Executive Engineer,
Provincial Division No.1,
PWD (B&R), Ambala Cantt